


Verre de protection externe 3M™ Speedglas™ 9002, standard 426000

Beschmermeruit buitenzijde

Accessories and spare parts**

Part No	Description	Part No	Description	Part No	Description
16 40 05	Ear and neck protection in leather.	40 11 90	Speedglas welding helmet 9000, without SideWindows, without filter.	42 80 10	Inner cover plate (53x103 mm) for 9002X/9000XF filters, pkg of 5. Plate marking 42 02 10.
16 40 09	Head protection, black/grey.	40 18 40	Speedglas welding helmet with SideWindows, with filter 9002D, dual shade 9/11.	42 80 20	Inner cover plate, +1 Shade for 9002D/9002V filters, pkg of 5.
16 75 20	Sweatband towelling, pkg of 2.	40 18 90*	Speedglas welding helmet 9000 with SideWindows, without headband, without filter.	42 80 30	Inner cover plate, +1 Shade for 9002X/9000XF filters, pkg of 5.
16 76 00	Sweatband towelling, pkg of 20.	42 20 00	Battery, pkg of 2.	42 80 40	Inner cover plate, +2 Shade for 9002D/9002V filters, pkg of 5.
16 80 00	Sweatband, leather.	42 60 00	Outer protection plate, standard, pkg of 10. Plate marking 42 01 50.	42 80 50	Inner cover plate, +2 Shade for 9002X/9000XF filters, pkg of 5.
16 80 10	Sweatband, fleecy cotton, pkg of 2.	42 70 00	Outer protection plate, scratch resistant, pkg of 10. Plate marking 42 01 00.	43 10 00	Battery cover, pkg of 2.
16 90 01	Neck protection, black/grey.	42 70 71	Outer protection plate, heat resistant, pkg of 10. Plate marking 42 01 71 HEAT.	43 20 00	Heat-reflecting front, silver.
16 91 00	Hood black/grey.	42 80 00	Inner cover plate (42x91 mm) for 9002D/9002V filters, pkg of 5. Plate marking 42 02 00.	43 20 15*	SideWindows cover plate (sticker), 5 pairs.
17 10 15	Holder for magnifying lens (not shown)			70 50 15	New headband (Sept 2012) with assembly parts.
17 10 20	Magnifying lens 1.0.			70 60 00	Assembly parts for headband.
17 10 21	Magnifying lens 1.5.				
17 10 22	Magnifying lens 2.0.				
17 10 23	Magnifying lens 2.5.				
17 10 24	Magnifying lens 3.0.				
40 00 40	Speedglas welding filter 9002D				
40 00 70	Speedglas welding filter 9002V				
40 00 80	Speedglas welding filter 9002X				
40 11 40	Speedglas welding helmet 9000, without SideWindows, with filter 9002D and headband.				

* Please use Part No 40 18 90 when new SideWindows are required.



** Speedglas welding helmets 9100, 9100 Air, 9100 FX and 9100 FX Air replaces the welding helmets 9000 and 9000 FlexView. Accessories and spare parts will remain for 3–5 years.