


INNER COVER PLATE 428010

Beschermruit binnenzijde

Verre de protection interne



* Speedglas 9100, 9100 Air, 9100 FX and 9100 FX Air Welding Helmets replaces the Speedglas 9000 and 9000 FlexView Welding Helmets.
Accessories and spare parts for 9000 series available for 3-5 years.

Accessories and spare parts*

Part No	Description	Part No	Description	Part No	Description
16 40 05	Ear and neck protection in leather.	42 60 00	Outer protection plate, standard, pkg of 10. Plate marking 42 01 50.	43 20 00	Heat-reflecting, front silver.
16 40 09	Head protection.	42 70 00	Outer protection plate, scratch resistant, pkg of 10. Plate marking 42 01 00.	43 20 15*	SideWindows cover plate (sticker), 5 pairs.
16 60 20	Assembly parts for headband.	42 70 71	Outer protection plate, heat resistant, pkg of 10. Plate marking 42 01 71.	43 30 00	Headband with air duct.
16 75 20	Sweatband, towelling, pkg of 2.	42 80 00	Inner cover plate (42x91 mm) for 9002D/9002V Filters, pkg of 5. Plate marking 42 02 00.	43 30 10	Air duct.
16 76 00	Sweatband, towelling, pkg of 2.	42 80 10	Inner cover plate (53x103 mm) for 9002X/9000XF Filters, pkg of 5. Plate marking 42 02 10.	43 30 60	Headband without air duct.
16 80 00	Sweatband, leather.	42 80 20	Inner cover plate, +1 Shade, for 9002D/9002V Filters, pkg of 5.	43 40 01	Face seal.
16 80 12	Sweatband, fleecy cotton, pkg of 2.	42 80 30	Inner cover plate, +1 Shade, for 9002X/9000XF Filters, pkg of 5.	43 50 00	Air spreader.
16 90 01	Neck protection black/grey.	42 80 40	Inner cover plate, +2 Shade, for 9002D/9002V Filters, pkg of 5.	44 28 00	9000 FlexView Welding Helmet for respiratory protection, without filter.
16 91 00	Hood black/grey.	42 80 50	Inner cover plate, +2 Shade, for 9002X/9000XF Filters, pkg of 5.	46 08 00	9000 Welding Helmet for respiratory protection, without welding filter.
17 10 20	Magnifying lens 1.0.	43 10 00	Battery cover, pkg of 2.	46 08 90*	9000 Welding Helmet without headband, without airduct.
17 10 21	Magnifying lens 1.5.			80 31 10	Tightening kit for Speedglas 9000 Welding Helmet, not shown.
17 10 22	Magnifying lens 2.0.				
17 10 23	Magnifying lens 2.5.				
17 10 24	Magnifying lens 3.0.				
40 00 40	Speedglas 9002D Welding Filter, dual shade 9/11.				
40 00 70	Speedglas 9002V Welding Filter, variable shade 9-13.				
40 00 80	Speedglas 9002X Welding Filter, variable shade 9-13.				
42 20 00	Battery, pkg of 2.				

* Please use Part No 46 08 90 to replace the SideWindows.