


169100 HOOD- MONNISKAP TECAWELD-CAGOUME TECAWELD



Accessories and spare parts

Part No	Description	Part No	Description	Part No	Description
16 80 15	Comfort sweatband, pkg of 3.	52 70 70	Outer protection plate, heat resistant, pkg of 10.	53 10 00	Battery holder, pkg of 2.
16 90 06	Head protection, (small).	52 80 05	Inner cover plate for 9100V filter, pkg of 5. Plate marking 117x50.	53 20 16	SideWindows cover plate, 2 pairs.
16 90 07	Head protection, (large).	52 80 06	Inner cover plate, +1 shade for 9100V filters, pkg of 3.	53 30 00	Speedglas headband 9100, with assembly parts.
16 90 10	Neck protection, black.	52 80 07	Inner cover plate, +2 shade for 9100V filters, pkg of 3.	53 35 00	Air duct.
16 91 00	Hood, black/grey.	52 80 15	Inner cover plate for 9100X filter, pkg of 5. Plate marking 117x61.	53 35 05	Adapter for non-QRS breathing tubes when using Speedglas welding helmet series 9100.
17 10 20	Magnifying lens 1.0.	52 80 16	Inner cover plate, +1 shade for 9100X filter, pkg of 3.	53 40 00	Face seal.
17 10 21	Magnifying lens 1.5.	52 80 17	Inner cover plate, +2 shade for 9100X filter, pkg of 3.	53 50 00	Air deflector.
17 10 22	Magnifying lens 2.0.	52 80 25	Inner cover plate for 9100XX filter, pkg of 5. Plate marking 117x77.	53 60 00	Pivot mechanism, left and right.
17 10 23	Magnifying lens 2.5.	52 80 26	Inner cover plate, +1 shade for 9100XX filter, pkg of 3.	53 61 00	Headband, front part.
17 10 24	Magnifying lens 3.0.	52 80 27	Inner cover plate, +2 shade for 9100XX filter, pkg of 3.	53 62 00	Headband, back part.
42 20 00	Battery, pkg of 2.			54 05 00	Front cover kit.
50 00 05	Speedglas welding filter 9100V.			54 18 90	Speedglas welding helmet 9100 FX Air, without filter, without face seal, without air duct, without headband.
50 00 15	Speedglas welding filter 9100X.			54 28 00	Speedglas welding helmet 9100 FX Air, without welding filter, with headband.
50 00 25	Speedglas welding filter 9100XX.			79 01 01	Product carry bag
52 30 00	Visor plate, standard, pkg of 5.				
52 30 01	Visor plate, anti-fog, pkg of 5.				
52 60 00	Outer protection plate, standard, pkg of 10.				
52 70 00	Outer protection plate, extra scratch resistant, pkg of 10.				

